

vDrive^{QL} Firmware Update 003

Before updating the firmware, check the existing version by executing the toolkit VINFO command. If the existing version of VDRV is 2.06 or lower, FSYS is 2.03 or lower, or TKQL is 1.08 or lower, then this update applies.

After the update VINFO will show:

VDRV v2.07
FSYS v2.03
TKQL v1.09

To update the firmware please refer to the latest version of the vDrive^{QL} user manual.

Patch Notes 20/04/19

- When executing the in-built toolkit, the error 'vDrive not responding' would occur. To fix this, in particular when a Super Gold Card or Super Gold Card clone was attached, the timings parameters for the side-channel communications have been relaxed to cover a wider timing window.
- Note: There have been a small number of reports of the 'vDrive not responding' error occurring on an unexpanded QL. The root cause of this error is yet to be determined but this update may help. If you have experienced this error then please contact me at vdrivezx@gmail.com with details of the occurrence.