

vDrive^{QL} Firmware Update 005

Before updating the firmware, check the existing version by executing the toolkit VINFO command. If the existing version of VDRV is 2.08 or lower, FSYS is 2.03 or lower, or TKQL is 1.08 or lower, then this update applies.

After the update VINFO will show:

VDRV v2.09

FSYS v2.03

TKQL v1.09

To update the firmware please refer to the latest version of the vDrive^{QL} user manual.

Patch Notes 12/07/26

- Minor bug fixes